



MEASURING BEARING *FRICTION* IN REAL-TIME

WHAT 8.5 BILLION FRICTION DATA
POINTS HAS TAUGHT US.



WHY WE MEASURE FRICTION

 **NTRS - NASA Technical Reports Server**

[Back to Results](#)

Design and fabrication of prototype system for early warning of impending bearing failure

Ball bearing performance tests run on several identical ball bearings under a variety of load, speed, temperature, and lubrication conditions are reported. Bearing temperature, torque, vibration, noise, strain, cage speed, etc., were monitored to establish those measurements most suitable as indicators of ball bearing health. Tape records were made under steady-state conditions of a variety of speeds and loads. Sample sections were selected for narrowband spectral analysis with a real time analyzer. An artificial flow was created across the inner race surface of one bearing using an acid etch technique to produce the scratch. Tape records obtained before and after established a characteristic frequency response that identifies the presence of the flow. The signals found most useful as indicators of performance degradation were ultrasonic outputs.

Document ID: 19720020851
Document Type: Contractor Report (CR)
Authors: Broderick, J. J. (Mechanical Technology, Inc. Latham, NY, United States), Burchill, R. F. (Mechanical Technology, Inc. Latham, NY, United States), Clark, H. L. (Mechanical Technology, Inc. Latham, NY, United States)
Date Acquired: September 2, 2013
Publication Date: January 1, 1972
Subject Category: MACHINE ELEMENTS AND PROCESSES
Report/Patent Number: MTI-71TR1, NASA-CR-123717
Funding Number(s): CONTRACT_GRANT: NAS8-25706
Distribution Limits: Public
Copyright: Work of the US Gov. Public Use Permitted.

Available Downloads


Name	Type
19720020851.pdf	STI


“The signals found most useful as indicators of performance degradation were ultrasonic outputs.”

The ultrasonic signal will appear prior to a temperature rise or increase in driving torque.”

HOW WE MEASURE FRICTION

IT IS SIMPLE, AS THE FRICTION IN THE BEARING INCREASES DUE TO LUBRICATION ISSUES OR THE ONSET OF FAILURE, THERE WILL BE A CORRESPONDING RISE IN ULTRASOUND (dB)






Up to
80%
of premature bearing failures can be traced to a problem with lubrication.

** SKF Bearing Corporation, Bearing Failures and Their Causes*


Coefficient of
FRICION



Viscosity x Rotational Speed / Load

USING ULTRASOUND TECHNOLOGY TO CONTINUOUSLY MONITOR THE BEARING FRICTION

- KNOW WHEN GREASED IS REQUIRED
- KNOW PRECISELY HOW MUCH IS REQUIRED



MONITOR AND TREND DECIBEL LEVELS CAUSED BY FRICTION - ISO29821-1

+8dB

**ABOVE BASELINE
INDICATES A LACK OF
LUBRICATION.**



+16dB

**ABOVE BASELINE
INDICATES DAMAGE TO
THE BEARING – A FAILURE
MODE BEYOND
LUBRICATION ALONE.**

+35dB

**ABOVE BASELINE
MEANS THE ASSET IS
CRITICAL – IT IS CLOSE
TO FAILURE.**

FRICTION TREND ON A MONTHLY ROUTE





**WHAT WE HAVE LEARNED
FROM MONITORING
*FRICTION***


IN REAL-TIME

USE CASE | FAN BEARING IN AN AIR HANDLER UNIT





- DRIVE END OF BELT DRIVEN FAN
- VARIABLE FREQUENCY DRIVE
- ADDITIONAL VIBRATION SENSORS
- REMOTE GREASE LINE

IDEAL FRICTION TREND IN A FAN BEARING IN AN AIR HANDLER UNIT



IDEAL FRICTION DISTRIBUTION IN A FAN BEARING IN AN AIR HANDLER UNIT



- **TRENDING NEAR THE BASELINE**
- **THROUGH ALL VARYING SPEEDS, THE FRICTION HAS A CONSISTENT CENTER POINT (AVERAGE)**
- **VALUES ARE NOT BOUNCING AROUND. (PEAK-TO-PEAK VALUES)**

WAIT....

**DOESN'T THE FRICTION CHANGE
BASED ON VARYING SPEED
CONDITIONS?**

**YES, BUT ONLY A LITTLE.... AND THIS IS WHAT IS
GREAT ABOUT ULTRASOUND AND MONITORING
FRICTION. IN A HEALTHY, PROPERLY LUBRICATED
BEARING THE FRICTION SHOULD NOT CHANGE
DRAMATICALLY. A SLIGHT INCREASE OF 2-3DB MAY BE
SEEN DEPENDING ON THE SPEED CHANGE.**

USE CASE BEARING IN ELECTRIC MOTOR






- NON-DRIVE END OF MOTOR
- USED FIN MOUNT

USE CASE FAN BEARING IN ELECTRIC MOTOR



NOTICEABLE IMPACTING IN THE BEARING

FRICITION DISTRIBUTION IN A BAD BEARING IN AN ECLECTIC MOTOR




- NOTICEABLE INCREASE IN FRICTION OVER 4 DAYS
- NOTICEABLE INCREASE IN THE PEAK-TO-PEAK VALUES.
- NO SINGLE POINT OF FRICTION LEVEL. BEARING IS BOUNCING AROUND

USE CASE | UNDER LUBRICATED BEARING



- DRIVE END OF MOTOR
- ONTRAK SMARTLUBE SYSTEM


USE CASE UNDER LUBRICATED BEARING




NOTICEABLE DECREASE IN FRICTION AFTER LUBRICATION

FRICITION DISTRIBUTION IN A UNDER LUBRICATED BEARING

BEFORE LUBRICATION




AFTER LUBRICATION




- NOTICEABLE DECREASE IN FRICTION AFTER LUBRICATION
- NOTICEABLE DECREASE IN THE PEAK-TO-PEAK VALUES.
- NOTICEABLE CENTER POINT ON THE HISTOGRAM

USE CASE UNDER LUBRICATED BEARING




NOTICEABLE DECREASE IN FRICTION AFTER LUBRICATION

USE CASE UNDER LUBRICATED BEARING




- NOTICEABLE DECREASE IN IMPACTING AFTER LUBRICATION
- MICRO EXPLOSIONS ARE GENERALLY THE FIRST SIGN OF LACK OF LUBRICATION

USE CASE UNDER LUBRICATED WITH A BAD BEARING




WITHIN A FEW HOURS OF LUBRICATION, THE FRICTION WAS BACK UP!

USE CASE UNDER LUBRICATED WITH A BAD BEARING



EVEN AFTER MULTIPLE LUBRICATION CYCLES DAYS APART


USE CASE 1.8 RPM BEARING




0.33 CC OF GREASE ADDED

IDENTICAL MOTORS WITH DIFFERENT FRICTION TRENDS



MOTOR #1 DRIVE END



MOTOR #1 NON-DRIVE END



IDENTICAL MOTORS WITH DIFFERENT FRICTION TRENDS



CAUSE: THERMAL EXPANSION FROM IMBALANCE

Work Order #:

Assessment Comment: An imbalance condition continues to exist on the fan.

Analysis Comment: The imbalance condition on the fan continues to be an issue. The overall amplitude in the Spectrum has increased going from 0.148 ips (inches per second) on May 2 to 0.259 ips (inches per second) on May 6. This has been reported prior and is probably the cause of looseness observed in the envelope spectrum.

Repair Recommendation: I recommend checking the runout of the motor shaft and fan hub where they mate. Inspect the blades for damages from impacts with the shroud. Inspect the shroud for impacts and clean any buildup that might be present. If the runout is less than 0.002", perform a precision balance, if greater, consider replacing the motor shaft. Consider looking at the bore of the fan hub and ensure it is centered.

MEASURING BEARING *FRICTION* IN REAL-TIME

WHAT 8.5 BILLION FRICTION DATA
POINTS HAS TAUGHT US.

ChrisH@UESystems.com

