



4WD SERVICE KITS



Added protection for harsh driving conditions
Designed to meet the demanding needs of 4x4 vehicles in the most challenging environments.



New vehicle warranties protected
You can protect the new car warranty of the vehicle you are about to service by using Ryco Filters. *



Genuine Performance
A superior performing filter must excel in 3 critical areas: Efficiency, Life and Flow.
Trust Ryco for Genuine Performance filters.



SCAN ME

For full kit listings see the back of this flyer, or check your vehicle listing online by scanning the QR Code to visit rycofilters.com.au or ryco.co.nz

RYCO
FILTERS

4WD SERVICE KITS

★ NEW PRODUCTS

		KIT CONTENTS				
MANUFACTURER	MODEL	KIT NUMBER	AIR	OIL	FUEL	CABIN AIR
FORD	Everest UA 3.2L	RSK58C	A1957	R2720P	R2724P	RCA227M†
FORD	Ranger PK (04-09-08/11), PJ (06/09-08/11), WL-AT, WE-AT	RSK4	A1541	Z418	Z699	
FORD	Ranger PX 2.2L & 3.2L (09/11../on) with radial air filter	RSK25C	A1784	R2720P	R2724P	RCA227P
FORD	Ranger PX 2.2L & 3.2L P4AT, P5AT, (01/11../on) with panel air filter	RSK58C	A1957	R2720P	R2724P	RCA227M†
HOLDEN	Colorado (RG), Colorado 7 (RG)	RSK29C	A1811	R2734P	R2733P	RCA182P
HOLDEN	Colorado RC, Rodeo RA;	RSK6	A1618	Z600	R2656P	
HOLDEN	Rodeo RA (4JH1)	RSK5	A1504	Z158	Z169A	
ISUZU	D-MAX 2021 ../on (option for automatic climate control variants)	RSK60C ★	A2040	Z929	R2619P	RCA423M
ISUZU	D-MAX 2021 ../on (option for manual A/C variants)	RSK61C ★	A2040	Z929	R2619P	RCA182M
ISUZU	D-MAX (07/12 - on), MU-X	RSK28C	A1828	Z929	R2619P	RCA182P
ISUZU	D-MAX (4JJ1 up to 05/12)	RSK6	A1618	Z600	R2656P	
MAZDA	BT-50 - With Climate control	RSK60C ★	A2040	Z929	R2619P	RCA423M
MAZDA	BT-50 - With manual A/C	RSK61C ★	A2040	Z929	R2619P	RCA182M
MAZDA	BT-50 DX	RSK7	A1541	Z632	Z699	
MAZDA	BT-50 UPOY, TD 2.2L & 3.2L, P4AT, P5AT (10/11../on), UR TD 2.2L & 3.2L, P4AT, P5AT (09/15../on)	RSK25C	A1784	R2720P	R2724P	RCA227P
MITSUBISHI	Pajero 3.2L NS, NT T/D (4M41)	RSK8	A1449	Z372	Z699	
MITSUBISHI	Triton 2.5L, ML/MN Turbo Diesel	RSK9	A1512	Z313	Z679	
MITSUBISHI	Triton 3.2L, (4M41)	RSK10	A1512	Z372	Z679	
MITSUBISHI	Triton ML/MN (4G64)	RSK39C	A1512	Z411	Z590	RCA206C
MITSUBISHI	Triton MQ, Pajero Sport QE	RSK53 AU	A1981	Z456	R2724P	
NISSAN	Navara (D40) (Thai built)	RSK34C	A1758	Z89A	Z1000	RCA230P
NISSAN	Navara D22 (ZD30)	RSK11	A1495	R2593P	Z332	
NISSAN	Navara D40 (Spanish Built)	RSK12C	A1598	Z89A	Z711	RCA174P
NISSAN	Navara/NP300 (D23) 2.3L TDi (YS23DDT/YS23DDTT)	RSK57C ★	A1943	R2660P	Z2851P	RCA182P
NISSAN	Patrol GU (TD42) Up to 2003	RSK13 AU	A444	Z503 x 2	Z332	
NISSAN	Patrol GU IV (TD42T)	RSK32	A1412	Z503 x 2	Z332	
NISSAN	Patrol GU IV (TD48DE)	RSK33	HDA5858	Z547	Z387	
NISSAN	Patrol GU IV, ZD30D (10/04-03/07)	RSK24	A1412	R2593P	Z332	
NISSAN	Patrol GU IV, ZD30D (10/04-03/07)	RSK24C	A1412	R2593P	Z332	RCA113P
NISSAN	Patrol GU Series 1 (TD42T)	RSK14 AU	A1412	Z416 ^{BP} Z503 ^{FF}	Z332	
NISSAN	Patrol GU ZD30D (09/07-on)	RSK30	A1412	R2593P	Z712	
TOYOTA	Fortuner GUN156R, 1GD-FTV 2.8L	RSK31C	A1876	Z418	R2777P	RCA333P
TOYOTA	Hilux GGN15R/GGN25R (1GRFE)	RSK35C	A1525	Z418	Z683	RCA164P
TOYOTA	Hilux GUN Series Turbo Diesel	RSK31C	A1876	Z418	R2777P	RCA333P
TOYOTA	Hilux KUN16 & KUN26	RSK2C	A1541	Z418	R2619P	RCA164P
TOYOTA	Hilux KUN16 & KUN26 (no cabin air filter)	RSK2	A1541	Z418	R2619P	
TOYOTA	Hilux KZN185, Landcruiser HZJ105, Prado KZJ97	RSK20	A1350	Z334	Z252X	
TOYOTA	Hilux LN167 & 172 (10/97../00)	RSK23	A1402	Z9	Z252X	
TOYOTA	Hilux LN86, 106, 107 & 111 (10/88../97)	RSK22	A310	Z9	Z252X	
TOYOTA	Hilux TGN121R (2TRFE)	RSK38C	A1876	Z418	Z684	RCA333P
TOYOTA	Hilux TGN16R (2TRFE)	RSK36C	A1541	Z418	Z684	RCA164P
TOYOTA	Hilux/Surf KN130 (1KZTE)	RSK19 NZ	A1335	Z334	Z252X	
TOYOTA	Landcruiser 76, 78 & 79 Series (1VD-FTV) up to 03/2019	RSK15	A1522	R2651P	R2657P	
TOYOTA	Landcruiser HDJ100R with 1HD-FTE Engines	RSK42	A1407	Z334	Z252Z	
TOYOTA	Landcruiser HDJ78/9	RSK1	A340	Z334	Z252X	
TOYOTA	Landcruiser HZJ105R with 1HZ Engines	RSK41	A1350	Z334	Z252Z	
TOYOTA	Landcruiser HZJ78, 79 (1HZ)	RSK26	A340	Z334	R2590P & Z252X	
TOYOTA	Landcruiser Prado FGRJ120 Petrol 4.0l	RSK17C	A1525	Z418	Z635	RCA104P
TOYOTA	Landcruiser Prado GDJ150 (1GD-FTV) 07/2015 - on	RSK40C	A1915	Z418	Z884	RCA164P
TOYOTA	Landcruiser Prado KDJ150/55R	RSK16C	A1522	Z418	Z699	RCA164P
TOYOTA	Landcruiser Prado KZJ120R	RSK3C	A1522	Z334	Z252X	RCA104P
TOYOTA	Landcruiser VDJ200	RSK18C	A1634	R2651P	R2657P	RCA164P
VOLKSWAGEN	Amarok 2H 340 TDI, 2H 400 TDI, 2H 420 TDI 2.0L Series	RSK27C	A1829	R2701P	Z951	RCA112P
TOYOTA	Landcruiser Prado KZJ120R	RSK3C	A1522	Z334	Z252X	RCA104P
TOYOTA	Landcruiser Prado KDJ150/55R	RSK16C	A1522	Z418	Z699	RCA164P
VOLKSWAGEN	Amarok 2H 340 TDI, 2H 400 TDI, 2H 420 TDI 2.0L Series	RSK27C	A1829	R2701P	Z951	RCA112P

AU Australia only, NZ New Zealand only, BP Bypass Filter, FF Full Flow Filter.† Interchangeable for superseded RCA277MS whilst stocks last. ★ NEW Product Release.