

RYCO

PRODUCT INFORMATION

4WD SERVICE KITS



ADDED PROTECTION FOR HARSH DRIVING CONDITIONS

Designed to meet the demanding needs of 4x4 vehicles in the most challenging environments.



NEW VEHICLE WARRANTIES PROTECTED

You can protect the new car warranty of the vehicle you are about to service by using Ryco Filters.*



GENUINE PERFORMANCE

A superior performing filter must excel in 3 critical areas: Efficiency, Life and Flow. Trust Ryco for Genuine Performance filters.

For full kit listings check your vehicle listing online at www.rycofilters.com.au or www.ryco.co.nz

*Conditions apply. Visit the New Vehicle Servicing section at the Ryco Filters website for full details.



RYCOFILTERS.COM.AU | RYCO.CO.NZ

BE RYCO READY

		KIT CONTENTS				
MANUFACTURER	MODEL	KIT NUMBER	AIR	OIL	FUEL	CABIN
FORD	Everest UA 3.2L, Ranger PX (with panel air filter)	RSK58C	A1957	R2720P	R2724P	RCA227M
FORD	Ranger (PJ & PK) 2.5L & 3.0L	RSK4	A1541	Z418	Z699	
FORD	Ranger PX	RSK25C	A1784	R2720P	R2724P	RCA227P
HOLDEN	Colorado RG, Colorado 7 RG	RSK29C	A1811	R2734P	R2833P	RCA182P
HOLDEN	Colorado RC, Rodeo RA	RSK6	A1618	Z600	R2656P	
HOLDEN	Rodeo RA (4JH1)	RSK5	A1504	Z158	Z169A	
ISUZU	D-MAX (07/12-07/20), MUX (12/13 - 06/21)	RSK28C	A1828	Z929	R2619P	RCA182P
ISUZU	D-MAX (4JJ1 up to 05/12)	RSK6	A1618	Z600	R2656P	
ISUZU	D-MAX 2021 ../on (option for manual A/C variants)	RSK61C	A2040	Z929	R2619P	RCA182M
MAZDA	BT-50 DX	RSK7	A1541	Z632	Z699	
MAZDA	BT-50 2021 ../on (suits automatic climate control variants)	RSK60C	A2040	Z929	R2619P	RCA423M
MAZDA	BT-50 UPOY Turbo Diesel (Radial Air Filter)	RSK25C	A1784	R2720P	R2724P	RCA227P
MITSUBISHI	Pajero NS, NT T/D (4M41)	RSK8	A1449	Z372	Z699	
MITSUBISHI	Triton 2.5 ML/MN Turbo Diesel	RSK9	A1512	Z313	Z679	
MITSUBISHI	Triton 3.2 (4M41)	RSK10	A1512	Z372	Z679	
MITSUBISHI	Triton ML/MN (4G64)	RSK39C	A1512	Z411	Z590	RCA206C
MITSUBISHI	Triton MQ	RSK53 ^{AU}	A1981	Z456	R2724P	
NISSAN	Navara D22 (ZD30)	RSK11	A1495	R2593P	Z332	
NISSAN	Navara D40 (Spanish Built)	RSK12C	A1598	Z89A	Z711	RCA174P
NISSAN	Navara D40 (Thai built)	RSK34C	A1758	Z89A	Z1000	RCA230P
NISSAN	Navara NP300 (D23) 2.3L TDi (YS23DDT/YS23DDTT)	RSK57C	A1943	R2660P	R2851P	RCA182P
NISSAN	Patrol GU (TD42) Up to 2003	RSK13	A444	Z503 x 2	Z332	
NISSAN	Patrol GU IV (TD42T)	RSK32	A1412	Z503 x 2	Z332	
NISSAN	Patrol GU IV (TD48DE)	RSK33	HDA5858	Z547	Z387	
NISSAN	Patrol GU IV (ZD30D) 10/04 - 03/07	RSK24	A1412	R2593P	Z332	
NISSAN	Patrol GU IV (ZD30D) 10/04 - 03/07	RSK24C	A1412	R2593P	Z332	RCA113P
NISSAN	Patrol GU Series 1 (TD42T)	RSK14	A1412	Z503	Z416 ^{BP} Z332 ^{FF}	
NISSAN	Patrol GU (ZD30D) 09/07../on	RSK30	A1412	R2593P	Z712	
TOYOTA	Fortuner, Hilux GUN Series Turbo Diesel	RSK31C	A1876	Z418	R2777P	RCA333P
TOYOTA	HiLux GGN15R/GGN25R (1GRFE)	RSK35C	A1525	Z418	Z683	RCA164P
TOYOTA	HiLux KUN16/26	RSK2	A1541	Z418	R2619P	
TOYOTA	HiLux KUN16/26	RSK2C	A1541	Z418	R2619P	RCA164P
TOYOTA	HiLux KZN185, LandCruiser HZJ105 & Prado KZJ95	RSK20	A1350	Z334	Z252X	
TOYOTA	HiLux LN167 & 172 (10/97 - 2000)	RSK23	A1402	Z9	Z252X	
TOYOTA	HiLux LN86, 106, 107 & 111 (10/88 ../97)	RSK22	A310	Z9	Z252X	
TOYOTA	HiLux TGN121R (2TRFE)	RSK38C	A1876	Z418	Z684	RCA333P
TOYOTA	HiLux TGN16R (2TRFE)	RSK36C	A1541	Z418	Z684	RCA164P
TOYOTA	LandCruiser 76, 78 & 79 Series (1VD-FTV) up to 12/2019	RSK15	A1522	R2651P	R2657P	
TOYOTA	LandCruiser 76, 78 & 79 Series (1VD-FTV) up to 12/2019	RSK15C	A1522	R2651P	R2657P	RCA414M
TOYOTA	LandCruiser HDJ100R with 1HD-FTE Engines	RSK42	A1407	Z334	Z252Z	
TOYOTA	LandCruiser HDJ78/9	RSK1	A340	Z334	Z252X	
TOYOTA	LandCruiser HZJ105R with 1HZ Engines	RSK41	A1350	Z334	Z252Z	
TOYOTA	LandCruiser HZJ78 & 79 (1HZ)	RSK26	A340	Z334	R2590P Z252X	
TOYOTA	LandCruiser Prado FGRJ120 4.0L	RSK17C	A1525	Z418	Z635	RCA104P
TOYOTA	LandCruiser Prado GDJ150 with (1GD-FTV) engines 2015 ../on	RSK40C	A1915	Z418	Z884	RCA164P
TOYOTA	LandCruiser Prado KDJ150/55R	RSK16C	A1522	Z418	Z699	RCA164P
TOYOTA	LandCruiser Prado KZJ120R	RSK3C	A1522	Z334	Z252X	RCA164P
TOYOTA	LandCruiser VCDJ200 (1VD-FTV) up to 03/2019	RSK18C	A1634	R2651P	R2657P	RCA164P
TOYOTA	LandCruiser VDJ200 (1VD-FTV) 04/2019 ../on	RSK62C	A1634	R2651P	R2888P	RCA164M
TOYOTA	LandCruiser VDJ76/78/79 (1VD-FTV) 01/2020 ../on	RSK63C	A1522	R2651P	R2888P	RCA414M
VOLKSWAGEN	Amarok 2.0L	RSK27C	A1829	R2701P	Z951	RCA112P

AU Australia only, BP Bypass Filter, FF Full Flow Filter.



RYCOFILTERS.COM.AU | RYCO.CO.NZ

